

Tele : 25673708

Asst Garrison Engineer (B&R)
AF Station Chandinagar
Baghpat (UP)-250615


19 Mar 2021

203/Gen/KV/17 /E2


Kendriya Vidyalaya
AF Station Chandinagar
Baghpat, UP-250615

**ISSUE OF STRUCTURAL STABILITY CERTIFICATE OF KENDRIYA VIDYALAYA
BUILDING AND BOUNDARY WALL FOR THE SESSION 2021-2022**

1. Please refer your letter No 260230/KV CN/2020-21/287 dt 17 Mar 2021.
2. On site inspection was carried out by the undersigned on 18 Mar 2021. The point observed are as under :-
 - (a) KV School building is structurally sound. However, some brickwork and plaster work is required.
 - (b) Boundary wall needs to be repaired.
 - (c) Periodical services are required.
3. This is for your information and necessary action please.


(Rahul Kumar)
Capt
AGE (B&R) Chandinagar

COUNTERSIGNATURE


(Y MM Reddy, IDSE)
EE
Garrison Engineer